

PRIORITY

OUT56082

T O P S E C R E T 302318Z

PRIORITY 4867

1965 JUN 30 23 27Z

25X1

IDEALIST

ATTENTION:

25X1

SUBJECT: EVALUATION OF MISSION C245C

1. CAMERA 119 WAS USED IN MISSION C245C FLOWN ON 30 APRIL 1965.
PROCESSING WAS ACCOMPLISHED IN THE FIELD.

1 JUL 1965

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION WAS GOOD.

B. 9R SIDE: A PROCESSING DENSITY CHANGE IS APPARENT IN FRAME 612. THERE IS A HEAT SPLICE BETWEEN FRAMES 674/675. SCOTCH TAPE WAS USED FOR A SPLICE BETWEEN FRAMES 1281/1282.

C. 9L SIDE: FRAMES 134 TO 137 ARE CRIMPED AND ARE ACCOMPANIED WITH PROCESSING MARKS. A PROCESSING DENSITY CHANGE IS PRESENT IN FRAME 773. THE SPLICES BETWEEN FRAMES 1099 TO 1100 AND 1185 TO 1186 APPEAR TO BE MADE WITH SCOTCH TAPE.

D. BOTH SIDES: ROLLER CHATTER IS PRESENT ON THE INBOARD EDGE THROUGHOUT THE MISSION. IRREGULAR PLUS DENSITY MARKS AND STREAKS APPEAR INTERMITTENTLY IN THE MISSION. THE LAST TITLED FRAME ON BOTH SIDES IS FRAME 1304.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY WAS GOOD.

B. PRINTING AND PROCESSING WAS ADEQUATE.

C. THE APPROXIMATE CLOUD COVER IS 35 PERCENT.

COPIES RECEIVED 7		
Cy No.	Office	Act.
✓	File	
	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
34	TID	✓
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

T O P S E C R E T

--END OF MESSAGE--

TOP SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1